

NEWS

NO. 209
MAY, 13, 2015

Dear Valued 555 Customers:

SANKEI INDUSTRY CO., LTD.
305 Takano, Ritto, Shiga, 520-3045, JAPAN
E-mail : info@sankei-555.co.jp

New Products

Catalogue page	555 NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
36	SE-3401R	HIJET	S200V	99-04	OUT R	60pcs	END OF SEPTEMBER
36	SE-3401L	HIJET	S200V	99-04	OUT L	60pcs	END OF SEPTEMBER
48	SR-T790	IPSUM	ACM26	01-09	R/L	40pcs	END OF SEPTEMBER
48	SR-T790-M	IPSUM	ACM26	01-09	R/L with 1 claw washer	40pcs	END OF SEPTEMBER
48	SR-T810	PRIUS V	ZW41 ZW41 (LX-TOURING PACKAGE)	11- 11-	R/L	40pcs	END OF SEPTEMBER
51	SR-N530	ALMERA	B10RS	06-	R/L	50pcs	END OF SEPTEMBER
51	SR-N530-M	ALMERA	B10RS	06-	R/L with 1 claw washer	50pcs	END OF SEPTEMBER
56	SR-1820R	BONGO FRIENDEE	SGEW	96-	R	40pcs	END OF SEPTEMBER
56	SR-1820L	BONGO FRIENDEE	SGEW	96-	L	40pcs	END OF SEPTEMBER
114	SL-3770R	TOWNACE	CR50	98-	FRONT R	100pcs	END OF SEPTEMBER
114	SL-3770R-M	TOWNACE	CR50	98-	FRONT R with 1 nut	100pcs	END OF SEPTEMBER
114	SL-3770L	TOWNACE	CR50	98-	FRONT L	100pcs	END OF SEPTEMBER
114	SL-3770L-M	TOWNACE	CR50	98-	FRONT L with 1 nut	100pcs	END OF SEPTEMBER

**THE BEST QUALITY PARTS
FROM THE MOST ADVANCED MFG. FACILITIES**

*Tie Rod End. Side Rod Assy. Ball Joint. Idler Arm.
Pitman Arm. Center Link. Drag Link. Inner Arm Shaft.*



ISO9001

New Products



Catalogue page	555 NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
123	SL-T800	SIENNA	ASL30	10-	FRONT R/L	40pcs	END OF SEPTEMBER
123	SL-T800-M	SIENNA	ASL30	10-	FRONT R/L with 2 nuts	40pcs	END OF SEPTEMBER

Note 1: New items are not listed on the back "555" catalogues (~Vol. 15).

Note 2: START (DELIVERY) indicates available date.

Product Information①

◆SE-7261 will be changed from Metal type to Plastic type as shown in the following pictures.




Product Information②

◆SL-1680/-M will be discontinued and superseded by SL-B010/-M.

※It will be changed May 1, 2015.




PL PAGE	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
134	SL-1680	LC62-34-170B ① LC62-34-170A	FAMILIA MPV	BJEP LW5W	00- 00-	FRONT R/L
134	SL-1680-M	LC62-34-170B-M ① LC62-34-170A-M	FAMILIA MPV	BJEP LW5W	00- 00-	FRONT R/L with 2 nuts



PL PAGE	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
138	SL-B010 (SL-1680)	MN101368 ① LC62-34-170B LC62-34-170A	OUTLANDER OUTLANDER USA GALANT FORTIS OUTLANDER SPORT DELICA FAMILIA MPV	CW5W CY4A GA2W CV4W, CV5W BJEP LW5W	05- 07- 07- 12- 07- 00- 00-	FRONT R/L
138	SL-B010-M (SL-1680-M)	MN101368-M ① LC62-34-170B-M LC62-34-170A-M	OUTLANDER OUTLANDER USA GALANT FORTIS OUTLANDER SPORT DELICA FAMILIA MPV	CW5W CY4A GA2W CV4W, CV5W BJEP LW5W	05- 07- 07- 12- 07- 00- 00-	FRONT R/L with 2 nuts

Product Information③

The dust cover will be changed as shown in the following pictures.



555 No.	The new shipment starts from
SB-2482	END OF MAY
SB-2722	END OF MAY
SB-2832	END OF MAY
SB-2852	END OF MAY

Part to be Discontinued

555 No.
SB-1212

※They are not available with this information.