

NEW NEWS

NO. 272

MARCH, 6, 2018

Dear Valued 555 Customers:

SANKEI INDUSTRY CO., LTD.
305 Takano, Ritto, Shiga, 520-3045, JAPAN
E-mail : info@sankei-555.co.jp

New Products

Catalogue page	555 NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
11	SE-A181R	86	ZN6	12-	OUT R	50pcs	MIDDLE OF JUNE
11	SE-A181L	86	ZN6	12-	OUT L	50pcs	MIDDLE OF JUNE
68	SR-H630	PILOT	YF3	09-	R/L	50pcs	MIDDLE OF JUNE
68	SR-H630-M	PILOT	YF3	09-	R/L with 1 claw washer	50pcs	MIDDLE OF JUNE
68	SR-H650	USA ODYSSEY	RL5	11-	R/L	40pcs	MIDDLE OF JUNE
68	SR-H650-M	USA ODYSSEY	RL5	11-	R/L with 1 claw washer	40pcs	MIDDLE OF JUNE
68	SR-H660	USA CR-V	RE	10-	R/L	40pcs	MIDDLE OF JUNE
68	SR-H660-M	USA CR-V	RE	10-	R/L with 1 claw washer	40pcs	MIDDLE OF JUNE
112	SB-H542	ACCORD HYBRID	CR6	13-	LOW R/L	70pcs	MIDDLE OF JUNE

Note 1: New items are not listed on the back "555" catalogues (~Vol. 17).

Note 2: START (DELIVERY) indicates available date.

Please refer to "Additional Applications", "Discontinued Items", "Correction of Additional Applications Information", "Correction of New Products Information" in the Following pages.

**THE BEST QUALITY PARTS
 FROM THE MOST ADVANCED MFG. FACILITIES**

*Tie Rod End. Side Rod Assy. Ball Joint. Idler Arm.
 Pitman Arm. Center Link. Drag Link. Inner Arm Shaft.*



ISO9001

Additional Applications

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
53	SR-T810	45510-47080LR ※ -47090LR ※ For GEAR ASSY 45510-47080 ※ -47090 ※	PRIUS A(ALPHA) ※	ZW4#. .CBU ※ ZW4#. .G ※	15- ※	R/L
132	SL-A110		C-HR ※	NGX50, ZYX10 ※	16- ※	FRONT R/L
132	SL-A110-M		C-HR ※	NGX50, ZYX10 ※	16- ※	FRONT R/L with 2 nuts

“※” marks the additions, not shown in the back issues of “555” catalog (~Vol. 17)

Discontinued Items

555 NO.	CAR NAME	MODEL	YEAR	POSITION
SA-T882R	COROLLA	AE111	95-	LOW R with BALL JOINT
SA-T882L	COROLLA	AE111	95-	LOW L with BALL JOINT


※The above products will be unavailable here after.

Correction of New Products Information

NEWS No. 261 dated June 16, 2017 had incorrect descriptions. Please revise the errors as follows and take note of "SB-H522" covers "51360-T5A-J11-1" & "51350-T5A-J01-1".

(WRONG)

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
112	SB-H522	51360-T5A-J11-1 @ 51350-T5A-J11-1 For ARM ASSY 51360-T5A-J11 51350-T5A-J11	FIT	GK3	14-	LOW R/L



(CORRECT)


Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
112	SB-H522	51360-T5A-J11-1 @ 51350-T5A-J01-1 For ARM ASSY 51360-T5A-J11 51350-T5A-J01	FIT	GK3	14-	LOW R/L

Correction of Additional Applications Information

NEWS No. 271 dated January 10, 2013 had incorrect descriptions. Please revise the errors as follows and take note of "SL-N570R-M" covers "54618-JK53E-M" & "54618-JK53C-M".

(WRONG)

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
148	SL-N570R-M	54668-JK53E-M @ -JK53C-M ※	INFINITI EX35 AWD SKYLINE(4WD) ※	J50 V36 ※	08- 06- ※	FRONT R with 2 nuts 1 washer



(CORRECT)

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
148	SL-N570R-M	54618-JK53E-M @ -JK53C-M ※	INFINITI EX35 AWD SKYLINE(4WD) ※	J50 V36 ※	08- 06- ※	FRONT R with 2 nuts 1 washer